

Fig. 1




Fig. 2




Fig. 3






Fig. 5



X15.0K 2.00μm



Bias Power: 60W

A high-contrast, black and white photograph showing a close-up of a textured surface, possibly a rock or mineral specimen. A prominent diagonal crack or fissure runs across the center of the image, separating the surface into two distinct areas. The texture appears rough and granular, with some areas showing more pronounced ridges and valleys. The lighting is dramatic, creating deep shadows and bright highlights that emphasize the surface irregularities.

Bias Power:100W

X15.0K 2.00 μ m

[illegible]

Fig. 9A




Fig. 9B




Fig. 10A




Fig. 10B




Fig. 11A




Fig. 11B




Fig. 12




Fig. 13




Fig. 14




Fig. 15A




Fig. 15D




Fig. 15B




Fig. 15E




Fig. 15C




Fig. 15F




Fig. 16





Fig. 17






Fig. 18A




Fig. 18B




Fig. 18C




Fig. 18D




Fig. 18E




Fig. 18F




Fig. 19A




Fig. 19B




Fig. 19C




Fig. 19D